

C-Print Crystal Textile Vinyl

Transparent material for application to textiles

Description

Transparent Heat seal material, specifically formulated for ink jet solvent and eco solvent based inks – printing and cutting systems or thermoresin. The material is very thin, suitable for light coloured fabrics.

Polyester backing.

Basic Information

Due to the many different base materials available on the market, the following heat transfer instructions are given as guideline only:

Temperature: 160-165°C

Time: 15"

Pressure: medium

Application Instructions

- 1) **Before printing, remove the additional, external protective film (very easy to detach).**
- 2) **Print in reverse**, on the layer previously covered with the protective film and cut the material
- 3) Let the print dry at least 12 hours before rolling, overlaying or heat transferring the material
- 4) Weed the exceeding material
- 5) Heat apply with its own polyester backing
- 6) Remove backing once **cold**

Suitable for

Cotton, polyester, poly-cotton blends.

Not suitable for treated and dyed garments (sublimation inks)

Washing: (wait 24h after the heat transfer)

50°C Max. – wash inside out - do not use bleach or other aggressive chemical agents

Dry-cleaning : no

Tumble drier : no

N.B. : all information given in this sheet are based on our experience

We recommend to always perform a test before starting standard production

We offer a wide range of **Grafflex Textile Vinyl's** which enables us to offer something suitable for every budget and application.

Tel: 01827 300500

Free Fax: 0800 318075 Web: www.grafityp.co.uk

E-mail: sales@grafityp.co.uk

GRAFITYP

Siser
THERMO TRANSFER FOR TEXTILES