

C-Print Glitter Textile Vinyl

Eye catching special effect material

Description

Glitter material, specifically formulated for ink jet solvent and eco solvent based inks – printing and cutting systems or thermoresin. Glitterprint is very opaque even on dark fabrics.

Polyester backing.

Basic Information

Due to the many different base materials available on the market, the following heat transfer instructions are given as guideline only:

Temperature: 165°C

Time: 15"

Pressure: medium

Application Instructions

- 1) Print and cut the material
- 2) Let the print dry at least 12 hours before rolling, overlaying or heat transferring the material
- 3) Weed the exceeding material
- 4) Remove from the backing using the **Siser transparent polyester T.T.D.** (adhesive, transparent polyester, resistant to high temperatures) or other application tapes
- 5) Heat apply
- 6) Remove application tape **hot**. Should you use other application tapes, follow the manufacturer's instructions

Suitable for

Cotton, polyester, poly-cotton blends.

Not suitable for treated and dyed garments (sublimation inks)

Washing: (wait 24h after the heat transfer)

50°C Max. – wash inside out - do not use bleach or other aggressive chemical agents

Dry-cleaning : no

Tumble drier : not advisable

N.B. : all information given in this sheet are based on our experience

We recommend to always perform a test before starting standard production

We offer a wide range of **Grafflex Textile Vinyl's** which enables us to offer something suitable for every budget and application.

Tel: 01827 300500

Free Fax: 0800 318075 Web: www.grafityp.co.uk

E-mail: sales@grafityp.co.uk

GRAFITYP

Siser
THERMO TRANSFER FOR TEXTILES